

Connector Pin Out:

AC Power Connector:

Pin	SIGNAL
1	Line
2	CHASSIS GND
3	Neutral

Output Power Connector (J1: 1x9 pin JST B9P-VH.)

Pin	SIGNAL
1	+48v
2	+48v
3	+48v
4	POWER GND
5	POWER GND
6	POWER GND
7	+12
8	-12
9	AGND

Auxiliary Power and Temp (J3 (1x5 JST B5P-VH) optionally (1x6 JST B5P-VH))

Optionally, a sixth pin header may be populated to bring out an extra -5v.

Pin	SIGNAL
1	+5v
2	+3.3v
3	AGND
4	TEMP MONITOR
5	STANDBY
6	-5 (optional)